

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:				
Company	Mike W. Glasson Environmental Coordinator			
OGM	Karl Houskeeper Environmental Scientist III			

Inspection Report

Permit Number:	C0070019		
Inspection Type:	PARTIAL		
Inspection Date:	Friday, January 23, 2004		
Start Date/Time:	01/23/2004 9:00:00 AM		
End Date/Time:	01/23/2004 10:00:00 AM		
Last Inspection:	Friday, December 19, 2003		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, ~Temperature 28 Degrees F

InspectionID Report Number: 159

Accepted by: pgrubaug 01/27/2004

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: CENTENNIAL MINE

Address: PO BOX 902, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: INACTIVE

Current Acreages		Mineral Ownership	Types of Operations	
5,419.49	Total Permitted	✓ Federal	✓ Underground	
35.27	Total Disturbed	✓ State	Surface	
	Phase I	☐ County	Loadout	
	Phase II	✓ Fee	Processing	
	Phase III	☐ Other	Reprocessing	

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Inspector's Signature:	Date	Friday, January 23, 2004
------------------------	------	--------------------------

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Friday, January 23, 2004 Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓			
2.	Signs and Markers	✓			
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	V
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	b Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070019
Inspection Type: PARTIAL

Inspection Date: Friday, January 23, 2004 Page 3 of 3

4.a Hydrologic Balance: Diversions

The culvert outlet (24"cmp) at the Aberdeen Truck Loadout was still 1/2 plugged. The outlet and disturbed diversion DD-4 need to be cleaned. This item was identified in both of the two previous inspections. In addition, it was noted in the inspector's field notes for the December 19, 2003, inspection that a roll of chain link fence was in the disturbed diversion DD-4. The roll of chain link fence was still in the diversion during the inspection. Pictures of the diversion, 1/2- 3/4 plugged outlet, and chain link fence in the diversion were taken during the inspection. Notice of Violation N04-49-2-1was issued for failure to maintain disturbed diversions DD-4 and the 24" cmp outlet adjacent to the Aberdeen Mine truck load out. The time for abatement to be accomplished on the violation is February 23, 2004.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment Pond E is located below disturbed diversion DD-4. Disturbed diversion DD-4 leads into sediment pond E. There was no offsite impact as a result of NOV N04-49-2-1.

4.d Hydrologic Balance: Water Monitoring

Third quarter 2003 water monitoring information is in the EDI website and uploaded. Fourth quarter 2003 water monitoring information is in the EDI website, but still needs to be reviewed and uploaded. Water monitoring is current.